Approved For Release 2007963705P. MASROP74B00499R000400050090-1

SECRET

FILE INFO			(W	hen Filled In)				
	c7157;	326		DUCTION PROHIB	ITED		:	 5 5 4
ACTION	1 1	DM	6	MASC	11 2	15DOG	16	
	2	/	7	FREA	12	1	17	
	3	/ 4	8	11	13	<i>Y</i>	18	
	4	15 A	9	DUBS	14		19	
*	5	D/2	1ø	SAS	15		2ø	

25×1	S	Ε	С	R	E	T	15Ø7Ø1Z	DEC	71	CITE	3:	542

25X1 REF:

IDEALIST DM-4

- I. THE ASTROSCIENCE GROUND STATION RECORDER/PLAYBACK UNITS, THE CEC'S, AND PATCHING EQUIPMENT HAS BEEN CHECKED. CAN'T FIND ANYTHING WRONG.
- 2. SINCE THIS IS FIRST TIME MISSION TAPES HAVE BEEN PATCHED

 USING THE NEWLY INSTALLED TROMPETER VIDEO JACKS/PLUGS, MAYBE A PATCH

 CORD WASN'T FULLY MATED WITH THE CORRESPONDING JACK.
- 3. SITUATION NOT HELPED SINCE CEC'S DO NOT HAVE PLAYBACK

 EQUALIZERS FOR ALL THE SPEEDS WE HAVE BEEN USING. 15, 30, AND 60 IPS

 HAVE BEEN REQUIRED SPEEDS, WITH 30 IPS MOST COMMON. WE NEED THE

 EQUALIZERS FOR 30 IPS, AS OUR 15 IPS EQUALIZERS ARE PRESENTLY IN THE

 30 IPS SLOT.
 - 4. PRESENT PLAN IS TO MOVE THE 15 IPS EQUALIZERS INTO PROPER SLOT AND PUT THE 60 IPS UNITS INTO THE 30 IPS SLOT. THIS WAY CAN MONITOR THE MOST FREQUENTLY UTILIZED DUPING SPEEDS TO INSURE SIGNAL IS BEING RECORDED.
 - 5. PREVIOUS REQUESTS FOR EQUALIZERS HAVE BEEN TURNED DOWN FOR

Approved Fer Release 2007/05/05: CFA-RDF74B00490R000400050090-1

SECRET

(When Filled In) FILE INFO

REPRODUCTION PROHIBITED					
ACTION	1 1	6	11	16	
	2	7	12	17	
	3	8	13	18	
	4	9	14	19	
	5	1ø	15	2ø	

3542 S E C R E T PAGE 2

> IF WE AGAIN SUBMIT A REQUISITION FOR "LACK OF FUNDS." QUERY:

ILLEGIB NECESSARY ITEMS, WHAT IS THE CHANCE FOR APPROVAL? NEEDED ITEMS ARE

28 EACH OF:

В.

CKT BOARD'S

HIGH FREQUENCY EQUALIZATION NETWORK 13-649-2HF(212269-2) Α.

CKT BOARD: LOW FREQUENCY EQUALIZATION NETWORK 13-649-2LF (212269-1)

BOTH ABOVE ITEMS MANUFACTURED BY CONSOLADATED ELECTRODYNAMICS CORPORATION, PASADENA, CALIF.

SECRET

BT

	ILLEGII